BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

	ame Of Work:	Providing and laying HDPE water line in HMT Layout Bangalore 1 in JP Park ward 17
	Administration Approval & Date	JC/RRN/AS/2244/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/291/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,98,000/-
5	Job Code No.	017-14-000012
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/229/13-14 Dtd: 07.02.2014
8	Work order Number & Date	EE/RRND/WO/229/13-14 Dtd: 07.02.2014
9	Contract Amount as per Agreement	Rs. 53,47,612/-
10	Bill Amount	Rs. 47,39,564=41
11	B.R No. & Date	255/14-15 Dtd: 28.06.2014
12	Agency	K Shivakumar
13	M.B. Number & Page No. of Measurement records	120/13-14 Page No 11950 to 11956
14	Date of Inspection	07.09.2017
15	Enclosures	4 Number of photos taken during inspection
16	The above site has been Inspected by me along with the Concerned person, as per EE(RRND) Letter No EE/RRN/PR/414/A/17-18 Dated 1-9-2017. It is observed that most of the Items indicated in the Xerox Copy of MB/XL Sheets are not susceptible for measurements, Inspection Report as the nature of work is Laying HDPE water Line, as such the photos taken during the execution of work have been scrutinised and Inspected, it appears that the above work has been done. The Items which are susceptible for measurements has been checked and found to be Satisfactory. This has a reference to the NOC Issued by Lokayukta vide Letter No LOK/INV(J)/CT/Crime 60/2014 Dated 1-8-2017	

7/9/2017

(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು - ...

Scanned by CamScanner